



中国认可
国际互认
检测
TESTING
CNAS L8082

IDFL # 19-282226

Test Report

Disa quilt medium

XS-55362
Zhejiang Samsung Down Co., Ltd

11 Mar 2019

Abby Han

Zhejiang Samsung Down Co., Ltd
No.288, Xiaoshao East Road, Xintang Street,
Xiaoshan District
Hangzhou, ZJ
CHINA

abby@samsungdown.com
langer@samsungdown.com
joyce.ye@icaglobalsourcing.com


RUSH 5-Day
Arrived: 01 Mar 2019
Completed: 11 Mar 2019

Sample Description: Quilt 98x98cm

Shipped By: STO7704570399121

Filling Label: Filling: 90% white duck down and 10% white duck feathers

Sample Identification: Disa quilt medium (Filling: white duck down 90% order: 48-03971 art: 134693)



This analysis represents (within normal testing variances) the test results from the sample(s) submitted. The analysis may not represent the entire lot, batch or production run. In no event shall IDFL be responsible or liable for any direct, indirect, punitive, incidental, special, or consequential damages whatsoever arising out of or connected with the use of, misuse of, or reliance upon such results or analysis. This test report is subject to the Terms and Conditions found at www.idfl.com.

IDFL LABORATORY AND INSTITUTE

IDFL CHINA
5F, Tonghui Mid-Road 688
Xiaoshan, Hangzhou, Zhejiang 311200
China
Tel: +86 571 8371 8685
email: china@idfl.com

IDFL USA
Tel: +1 801 467 7611
email: info@idfl.com

IDFL EUROPE AG
Switzerland
Tel: +41 52 765 1574
email: europe@idfl.com

IDFL TAIPEI
Taiwan
Tel: +886 2 2259 1178
email: taiwan@idfl.com

Security # 6298300593 e-Signature



www.idfl.com

Page: 1 of 3

Client: 2313

XS-55362

Sample: 1 of 1



中国认可
国际互认
检测
TESTING
CNAS L8082

IDFL # 19-282226

Test Report

Disa quilt medium

XS-55362
Zhejiang Samsung Down Co., Ltd

11 Mar 2019

Content Analysis EN 12131/12934

Total Down 87.8%
Waterfowl Feathers 10.6%
Other Elements 1.6%
Total 100.0%

Content Detail EN 12131/12934

Components EN 12131		Classification EN 12934	Waterfowl Elements	Other Elements
Down Cluster	85.7%	Down Cluster	85.7%	
Down Fiber	2.1%	Down Fibres Allowed in Down: 5% of Down Clusters = 4.3%	2.1%	
		Down Fibre over 5% Allowance		0%
		Total Down	87.8%	
Waterfowl Feathers	9.7%	Waterfowl Feathers	9.7%	
Feather Fiber	1.9%	Feather Fibre and Broken Damaged Feathers Allowed in Waterfowl Feathers: 9% of Waterfowl Feathers = 0.9%	0.9%	
Broken / Damaged Feathers	0.1%	Feather Fibre and Broken Damaged Feathers over 9% Allowance		1.1%
Total	2.0%	Total Feather	10.6%	
Quill / Long Feathers	0.0%	Quill / Long Feathers		0.0%
Landfowl	0.1%	Landfowl		0.1%
Residue	0.4%	Residue		0.4%
Total	100.0%	Total Other Elements		1.6%

Fill Power

Method	Conditioning	Final
IDFB/Lorch Cylinder (in ³ /30g)	Steam IDFB-10-B	740
EN Cylinder (cm ³ /g)	Tumble Dry EN 12130/PAS 1003	345.5
EN Cylinder (mm/20g)	Tumble Dry EN 12130/PAS 1003	106

Cleanliness Evaluation EN 12935

Oxygen EN 1162 1.6 mg/100g
Turbidity EN 1164 1000+ mm
1.77 NTU

This analysis represents (within normal testing variances) the test results from the sample(s) submitted. The analysis may not represent the entire lot, batch or production run. In no event shall IDFL be responsible or liable for any direct, indirect, punitive, incidental, special, or consequential damages whatsoever arising out of or connected with the use of, misuse of, or reliance upon such results or analysis. This test report is subject to the Terms and Conditions found at www.idfl.com.

IDFL LABORATORY AND INSTITUTE

IDFL CHINA
5F, Tonghui Mid-Road 688
Xiaoshan, Hangzhou, Zhejiang 311200
China
Tel: +86 571 8371 8685
email: china@idfl.com

IDFL USA
Tel: +1 801 467 7611
email: info@idfl.com

IDFL EUROPE AG
Switzerland
Tel: +41 52 765 1574
email: europe@idfl.com

IDFL TAIPEI
Taiwan
Tel: +886 2 2259 1178
email: taiwan@idfl.com

Security # 6298300593 e-Signature

www.idfl.com

Page: 2 of 3

Client: 2313

XS-55362

Sample: 1 of 1



中国认可
国际互认
检测
TESTING
CNAS L8082

IDFL # 19-282226

Test Report

Disa quilt medium

XS-55362
Zhejiang Samsung Down Co., Ltd

11 Mar 2019

End of Report

This analysis represents (within normal testing variances) the test results from the sample(s) submitted. The analysis may not represent the entire lot, batch or production run. In no event shall IDFL be responsible or liable for any direct, indirect, punitive, incidental, special, or consequential damages whatsoever arising out of or connected with the use of, misuse of, or reliance upon such results or analysis. This test report is subject to the Terms and Conditions found at www.idfl.com.



Security # 6298300593 e-Signature

IDFL LABORATORY AND INSTITUTE

IDFL CHINA
5F, Tonghui Mid-Road 688
Xiaoshan, Hangzhou, Zhejiang 311200
China
Tel: +86 571 8371 8685
email: china@idfl.com

IDFL USA
Tel: +1 801 467 7611
email: info@idfl.com

IDFL EUROPE AG
Switzerland
Tel: +41 52 765 1574
email: europa@idfl.com

IDFL TAIPEI
Taiwan
Tel: +886 2 2259 1178
email: taiwan@idfl.com

www.idfl.com

Page: 3 of 3

Client: 2313

XS-55362

Sample: 1 of 1